

Oil Analysis Identifies Source of Water in Dozer Power Shift Transmission



OVERVIEW

Client: Heavy Duty Equipment Distributor

Industry: Construction/Excavation

Oil Analysis Cost: \$8 per sample

Estimated Savings: \$50,000

SYNOPSIS

This case study illustrates how oil analysis determined the most likely source of excessive water contamination in a crawler dozer power transmission to be the result of improper storage and handling of the new lubricant supply.

BACKGROUND

During a scheduled preventive maintenance inspection (PM) of a Komatsu D155AX-8 Power Shift Transmission with 4,414 total hours since new, the maintenance technician observed several abnormal conditions. Among them, the technician reported that the machine required the addition of approximately one quart of coolant per week and the power shift transmission oil appeared to have water contamination.

Bureau Veritas Oil Condition Monitoring - 3385 Martin Farm Road, Suwanee, GA - 30024 800-241-6315

Sample Analysis Report • Status: ✔

Account Information		Sample Information		Other Sample Information	
Lab Customer ID#	Company Name	Lab No: 201609141443	Sample Tracking #	PO No:	
Company Worksite:	Company Address:	Sample Date: Sep 10, 2016	Completed Date: Sep 16, 2016	Work Order No:	Reference No: 6654824
Unit Information		Component Information		Fluid Information	
Unit ID:	Unit Mfg: Komatsu	Cprt. Description: TRANSMISSION	Cprt. Mfg: Komatsu	Fluid Manufacturer: MOBIL	Fluid Brand/Product: MOBILTRANS HD
Unit Model: D155AX-8	Unit Serial #:	Cprt. Model: D155AX-8	Cprt. Serial #:	Fluid Grade: SAE 30	
Unit Worksite: MEDLEY, FL		Cprt. Type: TRANSMISSION			

Maintenance Recommendations for Lab No: 201609141443
 Evaluated By: Master, Ross
 ANALYSIS INDICATES COMPONENT & LUBRICANT CONDITIONS ARE ACCEPTABLE. RESAMPLE AT THE NEXT SCHEDULED INTERVAL.

SPECTROCHEMICAL ANALYSIS IN PARTS PER MILLION																						
LAB NO.	SAMPLE DRAWN	Wear Metals					Contaminants					Additives										
		Iron	Chromium	Nickel	Aluminum	Lead	Copper	Tin	Silver	Thallium	Magnesium	Silicon	Sodium	Potassium	Barium	Molybdenum	Phosphorus	Zinc	Calcium	Boron	Magnesium	Antimony
1443	09/10/16	7	<1	<1	1	1	23	<1	<0.1	<1	<1	5	2	<1	5	1	1226	1458	3621	2	15	<1
1016	07/23/16	12	<1	<1	<1	6	1468	<1	0.1	1	<1	6	5	<1	5	<1	1336	1392	3506	6	13	<1
1370	01/29/16	18	<1	2	1	29	839 *	8	0.2	4	<1	10	4	1	5	1	930	1170	3963	9	10	1
1118	01/16/16	18	<1	<1	<1	26	815 *	3	<0.1	<1	<1	8	2	<1	3	2	1066	1322	4493	13	10	<1
0901	01/15/16	21	<1	2	<1	29	606 *	6	0.1	5	<1	12	7	1	7	1	1011	1206	4078	19	14	<1
0003	01/05/16	27	<1	3	4	14	499 *	<1	0.2	2	<1	13	33	<1	6	<1	846	848	1979	45	30	<1

SAMPLE INFORMATION		FLUID PROPERTIES/CONTAMINANTS					
LAB NO.	SAMPLE DRAWN	UNIT	UJOM	Water	D7279 Vis	GLY	Visual Filter
1443	09/10/16	7740	HR	<0.1	11.0	Test	
1016	07/23/16	69821	HR	<0.1	10.8		
1370	01/29/16	4631	HR	<0.1	7.7		
1118	01/16/16	4448	HR	0.5 *	9.4		
0901	01/15/16	4447	HR	1.6 *	9.3		
0003	01/05/16	4414	HR	8.0 *	11.2	NEG	Abnormal *

KEY: UoM - Unit of Measure Y - Yes N - No C - Changed S - Sampled > - Greater Than < - Less Than NIR - Not Reported (M) - Modified method
 Testing performed by Bureau Veritas, an ISO/IEC 17025:2005 accredited laboratory. LAA-B accredited Certificate Number 22264-3. Not in scope of accreditation. For further details on subcontracted testing, contact the laboratory directly. * This test is run based on a trigger test, in this case, * refers indicate that the trigger test was either not possible or the result was below the reporting limit. For a list of trigger tests refer to [http://www.bureauveritas.com/trigger-tests](#).
 Note: This analysis is intended as an aid in predicting mechanical wear. Test results, maintenance recommendations and accuracy are affected by customer provided sample, equipment identification, maintenance history and apply only to the sample as provided. No guarantee, expressed or implied, is made as to the condition of the equipment or component thereof. The ultimate responsibility for the maintenance of this piece of equipment and all of its components is the responsibility of the equipment owner.

www.bureauveritas.com/oil-analysis Page 1 of 1 © Copyright 2016, Bureau Veritas

*Note: For the purposes of this case study, customer- and equipment-specific information has been removed from this testing and analysis report with respect to customer data confidentiality.

CASE STUDY

Based on information provided by the customer and further observation, additional inspections were performed. An oil sample from the transmission was taken and submitted to the laboratory for testing and analysis while the equipment distributor continued investigations to determine the source of the water contamination.

Since the customer was adding at least a quart of coolant to the cooling system on a weekly basis, the assumption was that the transmission had an oil cooler leak inside the main radiator. The radiator was removed from the machine and the oil cooler removed from the radiator for a full inspection.

The oil analysis report confirmed that the sample was emulsified – water content was at 5% by volume. Copper was elevated but there were no coolant additives present and testing for glycol was negative – clear indications that the source of the water contamination was not from the cooling system.

The elevated water content will act as a catalyst for the formation of copper oxidizes from any copper alloy component, including the copper oil cooler. Elevated copper alone is usually from oil cooler oxides. All other wear metals were within acceptable limits. Having normal wear levels with high water content indicates the water contamination was occurring for a short period of time.

After inspection and testing, it was determined that the transmission's oil cooler was reported to be in satisfactory condition and no repairs were required. The oil cooler was reinstalled in the radiator and the radiator reinstalled in the machine. While an oil cooler leak had been eliminated as the source of the water ingress, the question remained – where was it coming from?

Further discussion and investigation also ruled out rain water, operating the machine in high water and high pressure water spray from cleaning as possible reasons for the contamination. It was determined that machine design would make rain water entry unlikely. The machine was then inspected for water marks that would indicate it was being used in water high enough to enter the transmission – none were noted – and the machine had not been cleaned with water at high pressure.

The only other typical explanation would be the improper handling and/or storage of a new oil supply. The new oil could have been delivered via a contaminated oil tote, lube truck tank or drum. Improper storage and handling of the new lubricant supply after delivery may have also resulted in contamination from the environment.




Figure 1

KEY FINDINGS

After reassembly of the radiator, and the transmission oil and oil filters were changed, another oil sample was taken within 33 operating hours. The water content had decreased to 1% by volume. The oil and filters were changed again and allowed to accumulate 1 hour of operation before sampling again. The water content was reduced to 0.5% by volume. The oil and filters were changed once again and allowed to run in service for 183 hours before sampling again. The third oil change water result was less than 0.1% by volume.




Figure 2

CONCLUSION

Even sealed drums that are allowed to stand upright and collect water on top will become contaminated. Condensation is a common source of contamination as is improperly installed or a lack of desiccant filters on totes or oil supply tanks. The overall condition of all new oil supply sources could not be inspected and may not be fully known by the owner of the machine. One contaminated drum of lubricant could be, and is the most likely, source of the contamination.

Water is one of the most common machine contaminants and when allowed to enter any mechanical component, elevated wear and reduction of service life will occur. This confirms the need for daily inspections by machine operators. Due to the excessive level of water in the transmission, premature wear or even failure would have occurred if not found and corrected in a timely manner.



CONTACT DETAILS

Los Angeles (USA West)	+1 800-424-0099	Netherlands	+31 10 472 04 22
Houston (USA South)	+1 800-248-7778	South Africa	+27(0) 61-091-1981
Chicago (USA North)	+1 800-222-0071	Saudi Arabia	+966-13-361-7960
Atlanta (USA East)	+1 800-241-6315	United Arab Emirates	+971 (4) 899-8100
Canada	+1 855-998-9899	China	+86 181 1600-8062
Mexico	+52 81 8335-7560	Japan	+81 (0)3 3436-5660
Spain	+34 943 25 69 35	Australia	+61 (0)8 8416-5237

E-Mail ocm@bureauveritas.com

Website www.bureauveritas.com/oil-analysis

